



# Construction through 3/31/19 - 1799 Building


#### **Work Underway**

- Roofing
- Exterior stucco walls

#### **Projected Work**

- Water and sanitary sewer testing
- Interior punch-list items





Front Elevation Aerial View

### Construction through 3/31/19 – Admin. Bldg.

#### **Work Underway**

- Interior metal stud and office storefront walls
- Exterior building walls
- Drywall installation
- Solar panel preparation
- MEP and fire protection system installation
- Interior painting
- Site grading
- Park and Ride lot concrete repair, paving and pavement markings

#### **Projected Work**

- Site grading
- Solar panel installation
- Exterior wall sheathing
- Fire protection system MEP installation
- Drywall installation
- Interior painting






Aerial Image of Site

Aerial Image of Building







Park and Ride Lot Grading

Front Entrance





Rear Entrance / Site Grading

**Detention Basin Area** 

Q






HR Office Area

Meeting Room







Center Stair