

An architectural rendering of a modern, multi-story building with a large glass facade and a stone-clad section on the right. The building is situated behind a parking lot with several cars parked. In the foreground, a blue SUV is partially visible. To the left of the building, there are trees and a small landscaped area with flags. The overall scene is bright and clear.

COMMISSION ADMINISTRATION BUILDING AT SCUDDER FALLS AND ADAPTIVE REUSE OF THE 1799 BUILDING



Delaware River
Joint Toll Bridge
Commission

Contract T-707A, January 23, 2019

Construction through 12/31/18 - 1799 Building

2

Work Underway

- Building being heated by heat pump system
- Interior painted

Projected Work

- Chimney stucco, weather permitting
- Water and sanitary sewer testing
- Interior punch-list items

1799 Building

3



Front Elevation

1799 Building

4



Lobby



Lobby and Restrooms

Construction through 12/31/18 – Admin. Bldg.

5

Work Underway

- ❑ Completed interior block walls
- ❑ Interior metal stud walls
- ❑ Exterior building walls
- ❑ Metal roof

Projected Work

- ❑ Site grading
- ❑ Roof system
- ❑ Metal stud walls
- ❑ MEP layout
- ❑ Exterior walls

Administration Building

6



Exterior – Front View



Exterior – Rear View

Administration Building

7



Exterior – Breakroom and Front Entrance



Exterior – West Wing

Administration Building

8



Second Floor – West Wing



Second Floor – East Wing