



Construction through 4/30/19 - 1799 Building

Work Underway

- Exterior stucco walls
- Exterior Railing

Projected Work

- Water and sanitary sewer testing
- Pedestrian/Bike Trail
- Interior punch-list items

1799 Building

2





Front Elevation Rear Elevation

Construction through 4/30/19 – Admin. Bldg.

Work Underway

- Interior office storefront walls
- Solar panel installation
- MEP and fire protection system installation
- Interior painting
- Site grading
- Underground stormwater system

Projected Work

- Site grading
- Solar panel installation
- Exterior wall sheathing
- Fire protection system MEP installation
- Interior painting
- Flooring

5





Aerial Image of Building

Aerial Image of Building

6





Underground Stormwater System

Underground Stormwater System













Second Floor Hallway







Finance Dept.

First Floor Hallway