

Scudder Falls Bridge Replacement Project

Construction Progress Photos

May - June 2017

Completed Construction Work to Date

- PA and NJ Advance Tree Clearing Work
- Pennsylvania Approach Roadway Noise Walls
- Pennsylvania Advanced Utility Work

PENNSYLVANIA

Construction of Trumbull's Lay-down/Staging Area on Route 332



Initial Construction of Trumbull's Lay-down/Staging Area on Route 332.



Construction Work Zone for shoulder closing on Route 332 On-Ramp to I-95NB.



Excavation for stormwater pre-treatment basin No. 1 along I-95 NB



I-95 Northbound Right Shoulder Build-up



Milling of existing shoulder on I-95NB



Completed Milling of I-95 NB Shoulder



Resurfacing right shoulder on I-95NB



Woodside Road Closure and Detour



Deck overlay construction on the Woodside Road bridge deck over the Delaware Canal.



**BRIDGE MONITOR/
ALL ELECTRONIC TOLLING
BUILDING
SITE**

Cleared Site



Grading of Building Site



MAIN RIVER BRIDGE

Installation of guide rail to allow for Construction Access to MRB along Route 29SB



Installation of Rock Construction Entrance for Construction Access along Route 29.



Construction access work along Route 29 SB for the Main River Bridge trestle.



Construction access work along Route 29 SB for the Main River Bridge trestle.



Construction access work along Route 29 SB for the Main River Bridge trestle.



Completed Rock Construction Entrance for Construction Access along Route 29.



Construction access work along Route 29 SB for the Main River Bridge trestle.



NEW JERSEY

Tree Clearing Rte. 29 Interchange



Setting Detour Signs



Covered Detour Signage in place



Installation of Inlet Protection within the Route 29 Interchange.



Route 29 Infield Grading for access and stormwater basin construction



Temporary Barrier and Crash Attenuators on Route 29 NB



Temporary Barrier on Route 29 SB



Temporary Barrier and Crash Attenuators on Route 29 SB

