

SCUDDER FALLS BRIDGE

REPLACEMENT
PROJECT



Construction Progress Photos
May – June 2018



SCUDDER FALLS BRIDGE REPLACEMENT PROJECT

PENNSYLVANIA APPROACH





PA Approach Median Barrier (Looking West)

PA Approach Median Barrier (Looking East)



PA Approach Underdrain construction



PA Approach Road Bed Preparation





Widened Woodside Road with Detour

Woodside Road Underdrain construction





SCUDDER FALLS BRIDGE REPLACEMENT PROJECT

Bridge Monitor/
AET Building Site



Building Perimeter Retaining Wall Construction



Building Perimeter Retaining Wall Construction



SCUDDER FALLS BRIDGE REPLACEMENT PROJECT

MAIN RIVER BRIDGE

Supports & Superstructure – Abutment 2 (NJ) to Pier 5



Roadway View Looking West



Abutment No. 1 (PA)





PIER 1 - Pier Cap Form

PIER 2 – Foundation Cap



PIER 2 – Column Reinforcing



PIER 2 – Completed Columns



PIER 3 – Cofferedam Preparation for Drilled Shafts





PIER 3 – Cofferedam Completed Drilled Shafts



PIER 4 – Drilled Shafts



PIER 4 – Pier Cap Reinforcing Steel



PIER 4 – Pier Cap Reinforcing Steel

Trestle Causeway Maintenance





SCUDDER FALLS BRIDGE REPLACEMENT PROJECT

NEW JERSEY



Route 29 Interchange Southerly Roundabout

Route 29 Interchange Southerly Roundabout



Route 29 Interchange Southerly Roundabout







I-95 NB Entrance Ramp Girder Erection



I-95 NB Entrance Ramp Completed Abutment 2



I-95 SB Exit Ramp Girder Erection



I-95 SB Exit Ramp Girder Erection



I-95 SB Exit Ramp Underpass Protection



I-95 SB Exit Ramp Concrete Deck Form Work



I-95 SB Exit Ramp Concrete Deck Form Work



Completed NJ Noise Wall Foundation Installation



NJ Noise Wall Posts



Project Site Aerial Photo

