

Scudder Falls Bridge Replacement Project

Construction Progress Photos

September – October 2017

PENNSYLVANIA

I-95 median T-Wall Construction



Backfilling T-Wall Retaining Wall within I-95 Median



Excavation for Stormwater Basin F



Widening and Drainage installation on Woodside Road



**BRIDGE MONITOR/
ALL ELECTRONIC TOLLING
BUILDING
SITE**

Preparation for Jacking of 72-inch pipe



MAIN RIVER BRIDGE

PA EarthCam Photo of MRB Construction



Drilled Shaft installation @ MRB Pier No. 1



PA Trestle Causeway Construction



NJ Trestle Causeway Construction



NJ Trestle Causeway Construction



Excavation within the MRB Pier No. 6 Cofferdam



NJ EarthCam Photo of MRB Construction



1959 Causeway Construction

View from New Jersey



Figure 4. Construction of SFB in 1959; view from New Jersey toward Park Island.

One Line Assembly of MRB Structural Steel



NEW JERSEY

Ramp 'C' Structure Pier and Abutment No. 1



Ramp 'G' Structure MSE Leveling Pad for Abut. No. 2

